



HydroPool Communication Bulletin

Date of Issue: 03/01/2024

Affected Model: All Signature and Swimspa

Affected Region: North America

Region to be distributed: North America

DEPARTMENT OF ISSUANCE: Parts & Accessories

SUBJECT: New Packs

Please distribute this memo to your applicable staff members and have them initial once reviewed and forwarded to the next party.

SYNOPSIS: Due to expanding functionality, new software is required to allow separate functions for separate brands. As a result, HP and Swimlife have their own **SEPARATE** packs.

OTHER INFORMATION:

For 2024, the in.ye6 (7505095) and in.ye0 (7505096) have been replaced by

7505110 - Spa Pack IN. YE-6 NA for HP

7505111 - YE-0 for YE-6 NA for HP

The switch to these new packs happened after the launch of the new line.

All spas made *after* 12/31/23 used the new packs.

However, because of backwards compatibility, you only need to order the new packs when replacements are required.

Due to the software change, if there are two existing packs, both will need to be changed when a replacement is needed.

Please consult your CSR or Parts Matrix for pricing in your region.

Thank You,

Parts and Accessories